



Photo 5. View north along Road 70 just south of the culvert.



Photo 6. View south along Road 70.



Photo 7. View of the tie in area to the south from the intersection of Road 70 and existing Line 1228.



Photo 8. View west from Road 70 of Line 1228 to be removed in Phase 1 Restoration Area.

Site Photos (Sheet 2 of 3)

Figure 5b